Z.	ROUTING AND TI	RANSMITTAL SLIP	Date	10/10	186	
TO: (Name, office symbol, room number, building, Agency/Post)				Initials	Date	
1.	Bob Kies	it, WOO				
2.	4					
3.						
4.						
5.						
	Action	File	Not	Note and Return		
_	Approval	For Clearance	Per	Per Conversation		
_	As Requested	For Correction	Pre	Prepare Reply		
-	Circulate	For Your Information	See	See Me		
-	Comment	Investigate	Sign	Signature		
-	Coordination	Inetify				

REMARKS

RECEIVED

OCT 1 4'86

EPA-WOO



DO NOT use this form as a RECORD of approvals, concurrences, disposals, clearances, and similar actions

Clearances, and similar actions					
FROM: (Name, org. symbol, Agency/Post)	Room No.—Bldg.				
Laxi Cohen m/s 525	Phone No. 440 - 1090				

5041–102 OPTIONAL FORM 41 Prescribed by GSA

OPTIONAL FORM 41 (Rev. 7-76) Prescribed by GSA FPMR (41 CFR) 101-11.206



ecology and environment, inc.

RECEIVED

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 208-624-9537

International Specialists in the Environmental Sciences

OCT 1 4 '86

MEMORANDUM

ED3 MUU

DATE: October 1, 1986

TO: John Osborn, FIT RPO, USEPA, Region X

THRU: D.A. Buecker, FIT RPM, E&E, Seattle

FROM: James Braddock, Geologist, E&E, Seattle JAB

Andrew Hafferty, Project Manager, E&E, Seattle

SUBJ: Correction to Final Report for Resource Recovery Corporation

Pasco, Washington Field Investigation

REF: TDD R10-8410-14

CC: Lori Cohen, USEPA, Region X Marsha Knadle, USEPA, Region X

The discrepancy between the elevation of monitoring well EE1 on the well log (Appendix A), lithology diagram (Figure 6.2), and the elevation of EE1 on the ground surface elevation map (Figure 6.1), has been resolved.

After a careful search through the survey, notes, and general field log book, it was determined that the elevation of EE1 is correct, and its position on the ground surface elevation map is incorrect. During the drilling program, the position of EE1 was changed twice because drillers encountered an impenetrable boulder layer. In each case, the drilling site was moved downhill and closer to the control well. The ground surface map shows the second abandoned site. According to the surveying notes, the true position of EE1 is 76 feet, in a direction South 50° East from the control well.

Please forward a copy of this memorandum to all individuals who received a copy of the report.